

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

ID1160  
NNE  
> 1  
1.528 mi.  
8067 ft.

MANHOLE 38640  
MCDONALD AV / AVE S  
BROOKLYN, NY

NY Spills S104283930  
N/A

Site 2 of 2 in cluster ID

Relative:  
Higher

Actual:  
22 ft.

SPILLS:

Name: MANHOLE 38640  
Address: MCDONALD AV / AVE S  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9909782 / 2002-03-29  
Facility ID: 9909782  
Facility Type: ER  
DER Facility ID: 82394  
Site ID: 91620  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1999-11-12  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 1999-11-12  
CID: 312  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-11-12  
Spill Record Last Update: 2002-03-29  
Spiller Name: Not reported  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL "  
Remarks: "2 PINTS UNK OIL 200GAL OF WATER - CASE #128956 - SAMPLE TAKEN - MARK TIBBE CONTACTED"

All Materials:

Site ID: 91620  
Operable Unit ID: 1084544  
Operable Unit: 01  
Material ID: 298852  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported